

Table of Contents

Version 1.4.0 (V1.4.0_200521) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.4.0 (V1.4.0_200521)

Release

2020-05-27

New Features and Improvements

1. Added feature to change device ID.
2. Enhancement in the security of the device.
 - Supports secure tamper.
 - Enhancement in security of encryption keys.
 - Restrict access through communications such as TCP/IP, RS-232, and USB.
 - Encrypt and migrate user information.
3. Changed the color of LED indicator.

Bug Fixes

1. A bug where OSDP Communication does not work normally if the value sent to the slave device is greater than the defined value.
2. A bug when a device is connected as a slave device after factory default, the 'Card Type' on the device setting page becomes inactivated.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:ber2_revision_note_140

Last update: **2021/06/01 13:06**