

Table of Contents

Version 1.6.1 (V1.6.1_201113) 1

 Release 1

 Bug Fixes 1

Version 1.6.1 (V1.6.1_201113)

Release

2020-11-13

Bug Fixes

1. Device shows low reading performance. (BEW2-OAPB)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_161

Last update: **2021/05/28 10:49**