

Table of Contents

Version 1.1.0 (V1.1.0_150819) 1

Release 1

Bug Fixes 1

Version 1.1.0 (V1.1.0_150819)

Release

2015-08-19

Bug Fixes

1. LSB recognition problem with DESFire cards.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_110_1

Last update: **2021/05/14 11:40**