

Table of Contents

1.6.2 Version (V1.6.2_180821) 1

Release 1

Bug Fixes 1

1.6.2 Version (V1.6.2_180821)

Release

2018-08-23

Bug Fixes

1. The device restarts when the fingerprint authentication fails.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_162

Last update: **2021/05/17 15:17**