

Table of Contents

Version 1.2.0 (V1.2.0_200604) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.2.0 (V1.2.0_200604)

Release

2020-06-05

New Features and Improvements

1. Added feature to change device ID.

Bug Fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_120

Last update: **2021/05/14 10:13**