

Table of Contents

Version 1.3.3 (V1.3.3_221118) 1

Release 1

Bug Fixes 1

Version 1.3.3 (V1.3.3_221118)

Release

2022-11-24

Bug Fixes

1. Dot(.) is not entered when configuring **IP address** after configuring a specific menu (Affects version: v1.0.0).
2. When the LAN cable connected to the device is disconnected and reconnected, it takes a long time for IP to be assigned by DHCP (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:fl_revision_note_133&rev=1669339706

Last update: **2022/11/25 10:28**