

Table of Contents

Version 1.3.0 (V1.3.0_200604)	1
Release	1
New Features and Improvements	1
Bug fixes	1

Version 1.3.0 (V1.3.0_200604)

Release

2020-06-05

New Features and Improvements

1. Added feature to change device ID.

Bug fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_130

Last update: **2021/05/18 08:44**