

Table of Contents

Version 1.3.2 (V1.3.2_230116) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.3.2 (V1.3.2_230116)

Release

2023-01-26

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.3.1 or higher.

Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

New Features and Improvements

1. Separated the log related to the cause of the door unlock.
 - Door open request by exit button
 - Door open request by operator
2. Added relay deactivation option for exit button input.
 - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.

Bug Fixes

1. Card types not checked to be used in smart card settings gets issued normally (Affects version: v1.0.0).
2. Event logs and real-time logs are not output due to corrupted log records (Affects version: v1.0.0).
3. Deleting all users included in an access group in BioStar 2 does not delete the access group from the device's user information (Affects version: v1.0.0).
4. Improved the structure to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xp2_revision_note_132

Last update: **2023/02/01 13:07**