

Table of Contents

Version 1.7.2 (V1.7.2_231102) 1

Release 1

Bug Fixes 1

Version 1.7.2 (V1.7.2_231102)

Release

2023-11-03

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.7.0 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

Bug Fixes

1. When running the Device Manager application v1.1.8 on iOS, certain devices do not connect. (Affects version: v1.7.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_172

Last update: **2023/11/27 14:52**