

Table of Contents

Version 2.6.3 (V2.6.3.16)	1
Date	1
Modified features	1

Version 2.6.3 (V2.6.3.16)

Date

2019-11-04

Modified features

1. Fixed the problem where the devices listed below may fail to connect when connecting.

- BioEntry Plus 2.0
- BioEntry W 2.0
- BioLiteNet 2.0
- Xpass 2.0
- Xpass Slim 2.0

2. Fixes a problem where the return value `dualIDSupported` and `useAlphanumericID` becomes 0 when `BS2_GetDeviceInfo` is called after directly connection a device by IP or port instead of searching for and connecting a device.

- Refer to API [BS2_SearchDevices](#)
- Refer to API [BS2_ConnectDevice](#)
- Refer to API [BS2_ConnectDeviceViaIP](#)
- Refer to API [BS2_GetDeviceInfo](#)
- Refer to structure [BS2SimpleDeviceInfo](#)

3. Fixes a problem where a timeout error (`BS_SDK_ERROR_TIMEOUT`) may occur if the devices listed below attempt a factory reset.

- BioEntry Plus 2.0
- BioEntry W 2.0
- BioLiteNet 2.0
- Xpass 2.0
- Xpass Slim 2.0
- Refer to API [BS2_FactoryReset](#)

4. Fixed a problem where the connection would be terminated normally if the device was disconnected and the packet was exchanged in the SDK without closing the connection yet.

From:
<https://kb.supremainc.com/kbtest/> - **BioStar Device SDK**

Permanent link:
https://kb.supremainc.com/kbtest/doku.php?id=en:release_note_26316

Last update: **2020/02/12 14:48**

