

# Table of Contents

**Version 2.9.1 (V2.9.1.0)**

Date

New Features

Modification function

1

1

1

2

# Version 2.9.1 (V2.9.1.0)

## Date

2023-02-23

## New Features

- Supports activating licenses for use of specific features on devices.
- QR code recognition and authentication support using the camera.
- Support setting the number of retries in case of socket read/write failure.
- Supports 3rd party OSDP reader connection.

### 1. Added device license activation feature.

- Add structure [BS2License](#)
- Add structure [BS2LicenseConfig](#)
- Add structure [BS2LicenseBlob](#)
- Add structure [BS2LicenseResult](#)
- Add API [BS2\\_GetLicenseConfig](#)
- Add API [BS2\\_EnableDeviceLicense](#)
- Add API [BS2\\_DisableDeviceLicense](#)
- Add API [BS2\\_QueryDeviceLicense](#)

### 2. Added features for QR code authentication by using the camera.

- Refer to structure [BS2BarcodeConfig](#)

### 3. Added retry count for communication used when an error occurs while reading or writing packets from the socket during communication.

#### CAUTION

Increasing the number of retries is a way to resolve temporary errors, but care must be taken as direct causes such as network disconnection occurs, can lead to wasted resources by meaningless read/write retries when reconnection is required.

- Add API [BS2\\_GetSocketRetryCount](#)
- Add API [BS2\\_SetSocketRetryCount](#)
- Add API [BS2\\_GetSocketSSLRetryCount](#)
- Add API [BS2\\_SetSocketSSLRetryCount](#)

### 4. Added feature to connect and manage 3rd party OSDP.

- Add structure [BS2OsdpStandardDevice](#)
- Add structure [BS2OsdpStandardDeviceAvailable](#)

- Add structure [BS2OsdpStandardNotify](#)
- Add structure [BS2OsdpStandardConfig](#)
- Add structure [BS2OsdpStandardActionConfig](#)
- Add structure [BS2OsdpStandardDeviceAdd](#)
- Add structure [BS2OsdpStandardDeviceUpdate](#)
- Add structure [BS2OsdpStandardDeviceCapability](#)
- Add structure [BS2OsdpStandardDeviceResult](#)
- Add structure [BS2OsdpStandardDeviceSecurityKey](#)
- Add API [BS2\\_GetOsdpStandardConfig](#)
- Add API [BS2\\_GetOsdpStandardActionConfig](#)
- Add API [BS2\\_SetOsdpStandardActionConfig](#)
- Add API [BS2\\_AddOsdpStandardDevice](#)
- Add API [BS2\\_GetOsdpStandardDevice](#)
- Add API [BS2\\_GetAvailableOsdpStandardDevice](#)
- Add API [BS2\\_UpdateOsdpStandardDevice](#)
- Add API [BS2\\_RemoveOsdpStandardDevice](#)
- Add API [BS2\\_GetOsdpStandardDeviceCapability](#)
- Add API [BS2\\_SetOsdpStandardDeviceSecurityKey](#)
- Add API [BS2\\_SetOsdpStandardDeviceStatusListener](#)
- Add callback function [OnOsdpStandardDeviceStatusChanged](#)

## Modification function

1. Fixed memory leak caused by network switches keepalive check being misunderstood by the SDK.
2. This is a problem that occurs only in version 2.8.3.2, and a problem that can lead to abnormal termination during user registration while taking a log dump inside the SDK has been fixed.
3. Fixes were made to stabilize the code internally in the SDK.

From:

<https://kb.supremainc.com/kbtest/> - **BioStar 2 Device SDK**

Permanent link:

[https://kb.supremainc.com/kbtest/doku.php?id=en:release\\_note\\_291](https://kb.supremainc.com/kbtest/doku.php?id=en:release_note_291)

Last update: **2023/08/17 13:30**