

Table of Contents

1.3.1 Version (V1.3.1_200702)	1
Release	1
Main Fixes	1

1.3.1 Version (V1.3.1_200702)

Release

2020-07-14

Main Fixes

1. Fingerprint authentication fails if the device is connected as a slave when using the ISO fingerprint template.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bln2_revision_note_131

Last update: **2021/05/28 08:31**