

Table of Contents

1.0.4 Version (V1.0.4_210303)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

1.0.4 Version (V1.0.4_210303)

Release

2021-03-10

New Features and Improvements

1. Suprema Thermal Camera (TCM10-FSF2) SDK Revision

- FPS 8.3 applied
- The management service is separated to recover the system safely after the device stops working abnormally.
- The infrared image motion stopped working or the device was restarted while using the thermal camera.
- The specifications of captured image buffer were modified.

Bug Fixes

1. The firmware version of the thermal camera was not displayed.
2. The previous T&A code setting was maintained even after changing the setting.
3. A timeout occurred when a user set to Exclude Device Default Authentication Mode attempted to authenticate a card on a slave device with authentication mode set to Card+PIN.
4. The thermal camera froze up when updating resources via BioStar 2.
5. Improved the Visual Face matching algorithm.
 - Improved the face recognition algorithm for users with glasses.
 - Improved the authentication performance when wearing masks.

From:
<https://kb.supremainc.com/knowledge/> -

Permanent link:
https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_104&rev=1622534024

Last update: **2021/06/01 16:53**