

Table of Contents

Version 1.8.1 (V1.8.1_250520)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.8.1 (V1.8.1_250520)

Release

2025-05-21

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.7.0 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (<https://supremainc.com>)

New Features and Improvements

1. Supports SL1, SL3, and SL1/SL3 Mix Mode for security level compatibility with MIFARE Plus EV1 cards.

- SL1: Compatible mode with MIFARE Classic
- SL3: Advanced security mode based on AES

2. Added identification code to support recognition of the latest cards.

- DESFire EV3

Bug Fixes

1. Custom smart cards with the **DESFire Advanced** option enabled fail to be recognized. (Affects version: v1.7.1)

2. Authentication fails with a 'period expired' message when using a smart card issued with a visual face included. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_181

Last update: **2025/05/22 10:15**