

Table of Contents

Version 1.2.1 (V1.2.1_161213) 1

Release 1

Bug fixes 1

Version 1.2.1 (V1.2.1_161213)

Release

2016-12-20

Bug fixes

1. Issue that cannot detect the device with UDP in BioStar 1.92.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_121

Last update: **2021/05/17 16:43**