

# Table of Contents

Version 1.5.4 (V1.5.4_230927) .....	1
Release .....	1
New features and improvement .....	1
Bug Fixes .....	1

# Version 1.5.4 (V1.5.4\_230927)

## Release

2023-10-24

For devices with the new SE processor, after upgrading the firmware to v1.5.3 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema.  
(supremainc.com)

## New features and improvement

1. Improved to select and update only the desired information when updating user information.  
(Compatible with BioStar v2.9.0 or higher)

## Bug Fixes

1. When authenticating with a BLE mobile card running on iOS, authentication fails and the device restarts intermittently. (Affects version: v1.4.0)
2. Deleting all users included in an access group in BioStar 2 does not delete the access group from the device's user information. (Affects version: v1.0.0)
3. Device does not recognize certain HID iCLASS Seos cards. (Affects version: v1.0.0)
4. Door Locked event occurs when input signal gets detected while configured to Arm/Disarm by input signal. (Affects version: v1.0.0)
5. Intermittently, the door does not open even if authentication succeeds when the door uses the slave device's relay. (Affects version: v1.0.0)
6. When a user registered in BioStar 2 is sent to the device and authenticated with a face or card, the user is intermittently not authenticated and the device restarts. (Affects version: v1.0.0)

7. Restart log is not logged in the device's **Event Log** when the master device is restarted. (Affects version: v1.5.3)
8. Global APB behavior for the same input was different depending on firmware version. (Affects version: v1.5.0)
9. When the device with the working **Screen Saver** is not used for a long time, a black screen occurs and the device freezes. (Affects version: v1.4.0)
10. Device abnormally restarts when changing the device's **Network** settings in BioStar 2. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:fs2\\_revision\\_note\\_154&rev=1698812469](http://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_154&rev=1698812469)

Last update: **2023/11/01 13:21**