

# Table of Contents

FaceStation F2 Revision Notes ..... 1

# FaceStation F2 Revision Notes

- After upgrading the firmware to v2.x.x, it is not able to downgrade to an earlier version (v1.x.x) firmware.
- When upgrading the firmware from v1.x.x to v2.x.x, it is recommended to use BioStar 2 or BioStar 2 Device SDK.
- When upgrading the firmware using a USB memory inevitably, first set **Menu Timeout to Always On** in the **Display & Sound** menu before proceeding with the upgrade. Also, even if a failure message is displayed during the upgrade, DO NOT remove the USB memory and wait until a success message is displayed. The device will restart automatically when the upgrade is complete.

- [Version 2.1.2 \(V2.1.2\\_230130\)](#)  
2023-02-01
- [Version 2.1.1 \(V2.1.1\\_221130\)](#)  
2022-11-30
- [Version 2.1.0 \(V2.1.0\\_221005\)](#)  
2022-10-05
- [Version 2.0.3 \(V2.0.3\\_220705\)](#)  
2022-07-15
- [Version 2.0.2 \(V2.0.2\\_220502\)](#)  
2022-05-10
- [Version 1.1.4 \(V1.1.4\\_220315\)](#)  
2022-03-22
- [Version 1.1.2 \(V1.1.2\\_210903\)](#)  
2021-10-01
- [Version 1.1.1 \(V1.1.1\\_210623\)](#)  
2021-06-25
- [Version 1.0.5 \(V1.0.5\\_210422\)](#)  
2021-05-06
- [Version 1.0.4 \(V1.0.4\\_210303\)](#)  
2021-03-10
- [Version 1.0.3 \(V1.0.3\\_210126\)](#)  
2021-02-02
- [Version 1.0.2 \(V1.0.2\\_210104\)](#)  
2021-01-05
- [Version 1.0.1 \(V1.0.1\\_201110\)](#)  
2020-11-13
- [Version 1.0.0 \(V1.0.0\\_200915\)](#)  
2020-09-15

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge./doku.php?id=en:tc\\_prod\\_f2&rev=1675906308](http://kb.supremainc.com/knowledge./doku.php?id=en:tc_prod_f2&rev=1675906308)

Last update: **2023/02/09 10:31**