

Table of Contents

Version 1.2.3 (V1.2.3_180907) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.2.3 (V1.2.3_180907)

Release

2018-09-20

New Features and Improvements

1. Enhance the solution for the relay processing and restoration.

Bug Fixes

1. The device does not recognize the iCLASS card intermittently.
2. Modified to exclude an incorrect input when the noise generated in the Wiegand input.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_123

Last update: **2021/05/28 11:14**