

Table of Contents

Version 1.3.1 (V1.3.1_170728)	1
Release	1
New Features and Improvements	1
Bug Fixes	1
Version 1.3.1 (V1.3.1_170710)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.3.1 (V1.3.1_170728)

Release

2017-07-31

New Features and Improvements

1. Support SEOS smart card settings

Bug Fixes

1. Issue where the device cannot recognize SEOS smart cards when multi-credential authentication mode (iCLASS SEOS smart card + Fingerprint) is used continuously.

Version 1.3.1 (V1.3.1_170710)

Release

2017-07-31

New Features and Improvements

1. Support SEOS smart cards.
2. Support validation of the device settings.
3. User Operator cannot change another user's Operator Level as Administrator.

Bug Fixes

1. Issue where the device is malfunctioned when device log is full.

2. Issue where the device is malfunctioned when receiving or sending Wiegand signals.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_131

Last update: **2021/05/13 14:15**