

Table of Contents

Version 1.0.1 (V1.0.1_160601) 1

Release 1

Bug fixes 1

Version 1.0.1 (V1.0.1_160601)

Release

2016-06-01

Bug fixes

1. Issue where the fingerprint sensor intermittently did not scan fingers.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_101

Last update: **2021/05/17 17:02**