

# Table of Contents

Version 1.4.1 (V1.4.1\_200902) ..... 1

Release ..... 1

New Features and Improvements ..... 1

Bug fixes ..... 1

## Version 1.4.1 (V1.4.1\_200902)

### Release

2020-09-25

### New Features and Improvements

1. Separated event logs of Mobile Access cards and RFID cards.
  2. Delete Change Device ID in CoreStation SETUP Manager user interface.
- Change Device ID not supported through CoreStation SETUP Manager.

### Bug fixes

1. Issue that the connection of the slave device is disconnected when the slave device is connected.
2. Hash key stored unencrypted.
3. An error occurs when a secure tamper occurs while upgrading the firmware version from 1.3.1 to 1.4.0.
4. When using a static IP while DNS server address is configured, a reboot on the device causes communication problems between the server.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:cs40\\_revision\\_note\\_141](https://kb.supremainc.com/knowledge/doku.php?id=en:cs40_revision_note_141)

Last update: **2021/05/25 08:27**