

Table of Contents

Version 1.5.1 (V1.5.1_210511)	1
Release	1
New Features and Improvements	1
Bug fixes	1

Version 1.5.1 (V1.5.1_210511)

Release

2021-05-24

New Features and Improvements

1. Upgraded to the 1.1.1i version of OpenSSL.
2. Increased maximum number of face users (1:N).
 - Before: 3,000
 - After: 4,000

Bug fixes

1. The device rebooted when the Supervised Input short circuit occurred without the CoreStation SETUP Manager IP being completely saved. (Affects version: v.1.3.1)
2. When calling the BS2_ResetConfigExceptNetInfo API from the BioStar 2 Device SDK, a 'Timeout' error occurred. (Affects version: v.1.0.0)
3. It failed to transfer user data during user synchronization as the face data size exceeded the maximum size allowed for the system. (Affects version: v.1.4.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:cs40_revision_note_151

Last update: **2021/05/25 08:20**