

Table of Contents

Version 1.4.2 (V1.4.2_210409)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.4.2 (V1.4.2_210409)

Release

2021-04-12

New Features and Improvements

1. Replaced with a new LCD screen.

After upgrading the firmware to v1.4.2, you cannot downgrade the firmware to the previous version that includes the kernel and U-Boot.

2. Added minimum and maximum threshold temperature functions.

- Temperature input range: 1-45°C
- Default value of minimum threshold temperature: 32°C

Bug Fixes

1. The thermal camera froze up when updating resources via BioStar 2.

From:
<http://kb.supremainc.com/knowledge/> -

Permanent link:
http://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_142

Last update: **2021/05/12 08:47**