

Table of Contents

Version 2.0.3 (V2.0.3_220705) 1

Release 1

Bug Fixes 1

Version 2.0.3 (V2.0.3_220705)

Release

2022-07-15

Bug Fixes

1. Stuck in migration progress after upgrading the firmware (Affects version: v2.0.2).
2. Fingerprint sensor not responding after upgrading FSF2-ODB from v1.1.0 to v2.0.2 (Affects version: v2.0.2).

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_203

Last update: **2022/08/24 14:51**