

Table of Contents

Version 1.0.1 (V1.0.1_191030) 1

Release 1

New features and improvements 1

Bug fixes 1

Version 1.0.1 (V1.0.1_191030)

Release

2019-11-07

New features and improvements

1. Added a logic to prevent FA(False Acceptance) for the fingerprint authentication.
2. Applied the latest Android security patch.
 - Patch level: August 5, 2019.
3. Support for the Ethernet setting API.
4. Remove some Android applications
 - Improved the issue that error messages occur caused by some unnecessary applications.

Bug fixes

1. Android OS reboots intermittently after the fingerprint sensor is reset.
2. The device reboots abnormally if a user leaves the AP unconnected after turning on the Wi-Fi.
3. The device reboots if a user authenticates the fingerprint consecutively for a long time.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:omnis_revision_note_101

Last update: **2021/05/18 10:20**