

Table of Contents

Version 1.3.1 (V1.3.1_220103)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.3.1 (V1.3.1_220103)

Release

2022-01-05

New Features and Improvements

1. Improvements related to RS-485 communication.

Bug Fixes

1. Device ID value changed to 0 abnormally (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_131

Last update: **2022/01/27 11:30**