2024/01/01 19:37 1/1 Version 2.8.0 (V2.8.0.6)

Table of Contents

Version 2.8.0 (V2.8.0.6)	1	L
Date	1	L
New Features		L
Modified Features	2)

2024/01/01 19:37 1/3 Version 2.8.0 (V2.8.0.6)

Version 2.8.0 (V2.8.0.6)

Date

2021-06-07

New Features

- Supports X-Station 2
- Supports Intelligent Slave Feature (FW upgrade is required)
- Supports getting Face Image Warping (FaceStation F2 only)
- Supports the function of Device Capabilities to know the connected device capability
- Adds the relevant log events of Mobile Card Verification
- Adds new model names to check card supporting
- 1. X-Station 2 Configurations are available to use.
 - Structure BS2BarcodeConfig has been added
 - API BS2 GetBarcodeConfig has been added
 - API BS2 SetBarcodeConfig has been added
 - API BS2 WriteQRCode has been added
- 2. The relevant function of Intelligent Slave is available to use. Intelligent Slave is a function that enables many users' 1:1 or 1:N matching by transmitting the authentication result to OSDP card data when authentication using biometrics is performed in an environment in which the Suprema biometric device and a third-party controller are connected. Intelligent Slave Support
 - Refer to structure BS2Rs485Config
 - Refer to API BS2 GetRS485Config
 - Refer to API BS2 SetRS485Config
- 3. Getting Image Warping from the raw image file of user face is available to use.
 - Refer to API BS2 GetNormalizedImageFaceEx
- **4.** Getting Device Capacity Information has been added.
 - Refer to structure BS2DeviceCapabilities
 - Refer to API BS2 GetDeviceCapabilities
- **5.** New log event 'Mobile Card Verification' has been added to distinguish the user credential.
 - Refer to structure BS2Event and refer to the subcode
- **6.** API BS2_GetCardModel has been added to support the below model names.
 - Refer to API BS2 GetCardModel

2024/01/01 19:37 2/3 Version 2.8.0 (V2.8.0.6)

- BEW2-ODPB
- BEW2-OAPB
- BEW2-OHPB

Modified Features

1. Fixed the error BS_SDK_ERROR_TIMEOUT where the below case.

RS485 Master: CoreStation 40

RS485 Slave: FaceStation 2 / FaceLite

Assigning a face template for FaceStation 2 or FaceLite to a user and enrolling it on CoreStation 40.

- Refer to API BS2 EnrolUser
- Refer to API BS2 EnrollUser
- Refer to API BS2 EnrolUserEx
- Refer to API BS2 EnrollUserEx
- Refer to API BS2 EnrollUserSmall
- Refer to API BS2 EnrollUserSmallEx
- Refer to API BS2 EnrollUserFaceEx
- 2. Fixed the issue that device transfers for more than 700 users were relatively slow compared to V2.7.2.x and earlier.
 - Refer to API BS2 EnrolUser
 - Refer to API BS2 EnrollUser
 - Refer to API BS2 EnrolUserEx
 - Refer to API BS2 EnrollUserEx
 - Refer to API BS2 EnrollUserSmall
 - Refer to API BS2 EnrollUserSmallEx
 - Refer to API BS2 EnrollUserFaceEx
- **3.** Fixed the return value from BS_SDK_SUCCESS to BS_SDK_ERROR_NOT_SUPPORTED when requesting Config from FaceLite that does not support Event config.
 - Refer to API BS2 GetEventConfig
- **4.** Fixed the issue that the SDK allocation and release were repeated, making device connection impossible if a certain number of times were exceeded.
 - Refer to API BS2 AllocateContext
 - Refer to API BS2 ReleaseContext
- **5.** Fixed the issue that calling BS2_ReleaseContext cannot release the resource intermittently and the port 51212/port 51213 occupied.
- **6.** Fixed the issue that a deadlock could occur during event processing due to repeated connecting device/disconnecting device calls.

2024/01/01 19:37 3/3 Version 2.8.0 (V2.8.0.6)

- 7. Fixed the issue that the application may crash intermittently during calling BS2 ReleaseContext.
- **8.** Fixed the issue that the device could be reset if the fields of timeout were not assigned a multiple of 10 when updating the display settings.
 - Refer to structure BS2DisplayConfig menuTimeout, msgTimeout, backlightTimeout
 - Refer to API BS2 SetDisplayConfig
- **9.** Fixed the issue that CPU Usages goes up to 99% when BS2_SearchDevices is called repeatedly in a 4-core environment.
- 10. FaceStation F2 Only The meaning and setting values of lightCondition in the BS2FaceConfig have been changed as follows.

1	Supported Ver.	Meaning	0	1	2	3
As-Is	1.0.0 ~ 1.0.5	Ambient Brightness	Indoor	Outdoor	Auto	-
То-Ве	1.1.0 or higher	Light Brightness	Normal	High	- (Deprecated)	Not used

Refer to structure BS2FaceConfig lightCondition

From:

https://kb.supremainc.com/bs2sdk/ - BioStar 2 Device SDK

Permanent link:

https://kb.supremainc.com/bs2sdk/doku.php?id=en:release note 280&rev=1623030000

Last update: 2021/06/07 10:40