

Table of Contents

Version 1.2.0 (V1.2.0_160106)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.2.0 (V1.2.0_160106)

Release

2016-01-06

New Features and Improvements

1. Support for scheduled lock/unlock zones.
2. Support for global anti-passback.

Bug Fixes

1. Door relay not working properly after restarting the device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_120

Last update: **2021/05/14 11:42**