

# Table of Contents

Version 1.2.1 (V1.2.1_161213) .....	1
Release .....	1
Bug fixes .....	1

## Version 1.2.1 (V1.2.1\_161213)

### Release

2016-12-20

### Bug fixes

1. Issue that cannot detect the device with UDP in BioStar 1.92.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2\\_revision\\_note\\_121](http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_121)

Last update: **2021/05/17 16:43**