

# Table of Contents

|                                     |   |
|-------------------------------------|---|
| Version 1.2.2 (V1.2.2_170213) ..... | 1 |
| Release .....                       | 1 |
| New Features and Improvements ..... | 1 |
| Bug fixes .....                     | 1 |

# Version 1.2.2 (V1.2.2\_170213)

## Release

2017-02-27

## New Features and Improvements

1. Add Lift I/O MFG Command.
2. Clean up the unused thread

## Bug fixes

1. Issue where the slave device's time zone is changes when the device synchronization is perfomed.
2. Wiegand Output malfunctions when fingerprint authentication is completed after authenticating with the unregistered card.
3. Slow-downs the performance.
4. Issue that cannot check the individual log after the authenticating the card.

From:  
<http://kb.supremainc.com/knowledge/> -

Permanent link:  
[http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2\\_revision\\_note\\_122](http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_122)

Last update: **2021/05/17 16:41**