

Table of Contents

Version 1.5.5 (V1.5.5_240821)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.5.5 (V1.5.5_240821)

Release

2024-08-26

For devices with the new SE processor, after upgrading the firmware to v1.5.3 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema.

(<https://supremainc.com>)

New Features and Improvements

1. Improved to get user update succeeded event log using the GetLogWithFilter function in the SDK.
2. Improved to ensure that values set with osdp_comset are correctly applied on the device connected as a slave.

Bug Fixes

1. Authentication result is displayed when accessing the admin menu via facial authentication. (Affects version: v1.5.2)
2. The user ID stored as a 32-character string is truncated to only 31 characters in a specific event log. (Affects version: v1.0.0)
3. When a user with a 32-character user ID authenticates to the device while the device is not connected to the server, the authentication event log is not updated in BioStar 2 even after the device is reconnected to the server. (Affects version: v1.0.0)
4. Deleted image logs from the device gets continuously uploaded to the server. (Affects version: v1.5.2)
5. When entering the **Wireless**, duplicate SSID are displayed. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_155

Last update: **2024/08/29 10:42**