

# Table of Contents

Version 1.1.0 (V1.1.0_160407) .....	1
Release .....	1
Bug fixes .....	1

# Version 1.1.0 (V1.1.0\_160407)

## Release

2016-04-07

## Bug fixes

1. Logs not transmitting properly when logs in the device reaches the storage limit.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2\\_revision\\_note\\_110](https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_110)

Last update: **2021/05/13 14:54**