

# Table of Contents

Version 1.3.1 (V1.3.1_170728) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1
Version 1.3.1 (V1.3.1_170710) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

## **Version 1.3.1 (V1.3.1\_170728)**

### **Release**

2017-07-31

### **New Features and Improvements**

1. Support SEOS smart card settings

### **Bug Fixes**

1. Issue where the device cannot recognize SEOS smart cards when multi-credential authentication mode (iCLASS SEOS smart card + Fingerprint) is used continuously.

## **Version 1.3.1 (V1.3.1\_170710)**

### **Release**

2017-07-31

### **New Features and Improvements**

1. Support SEOS smart cards.
2. Support validation of the device settings.
3. User Operator cannot change another user's Operator Level as Administrator.

### **Bug Fixes**

1. Issue where the device is malfunctioned when device log is full.

## 2. Issue where the device is malfunctioned when receiving or sending Wiegand signals.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2\\_revision\\_note\\_131](https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_131)

Last update: **2021/05/13 14:15**