

Table of Contents

Version 1.4.1 (V1.4.1_200902)	1
Release	1
New Features and Improvements	1
Bug fixes	1

Version 1.4.1 (V1.4.1_200902)

Release

2020-09-25

New Features and Improvements

1. Separated event logs of Mobile Access cards and RFID cards.
 2. Delete Change Device ID in CoreStation SETUP Manager user interface.
- Change Device ID not supported through CoreStation SETUP Manager.

Bug fixes

1. Issue that the connection of the slave device is disconnected when the slave device is connected.
2. Hash key stored unencrypted.
3. An error occurs when a secure tamper occurs while upgrading the firmware version from 1.3.1 to 1.4.0.
4. When using a static IP while DNS server address is configured, a reboot on the device causes communication problems between the server.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:cs40_revision_note_141

Last update: **2021/05/25 08:27**