

Table of Contents

Version 1.0.3 (V1.0.3_170919)	1
Release	1
Bug Fixes	1

Version 1.0.3 (V1.0.3_170919)

Release

2017-09-19

Bug Fixes

1. Issue where the device transfer to server the previous firmware version information after upgrading the firmware.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_103_2

Last update: **2021/05/12 10:29**