Table of Contents

Version 1.4.0 (V1.4.0 20091	8)
	ements
•	

Version 1.4.0 (V1.4.0_200918)

Release

2020-09-28

New Features and Improvements

- 1. Added feature to change device ID.
- 2. Enhancement in the security of the device.
- Restrict unencrypted connections.
- Enhancement in the security of encryption keys.
- Encrypt and migrate user information.
- 3. Improved Anti-passback zone to operate based on the door status.
- 4. Improved the scheduled unlock zone function for each floor when controlling elevator.
- **5.** Supports server matching.
- 6. Supports the Mobile Access V1.1.
- 7. Supports the thermal camera.
- 8. Supports the Screen Saver.
- 9. Improved the face recognition algorithm for users with glasses.
- 10. Supports the new face template.
- Face templates scanned or enrolled on devices with the firmware version 1.4.0 or later are not compatible with devices with firmware version 1.3.1 or earlier, and authentication may fail due to this incompatibility.
- If the firmware of the face recognition device connected as a slave is the latest version (FaceStation 2: 1.4.0 or later, FaceLite: 1.2.0), authentication may fail because it is not compatible with the existing template.
- 11. Increased maximum number of users (1:N).

Before: 3,000After: 4.000

- 12. Supports new device.
- XPass D2 (Rev 2)

Main Fixes

- 1. When all or user data were exported to a USB and then the user data were imported again after upgrading the device firmware, the event log was deleted.
- 2. Logs generated while the device is disconnected are not sent to BioStar 2, even after the device is reconnected.

Bug Fixes

- 1. Added feature to change device ID.
- 10. Supports the new face template.

From:

http://kb.supremainc.com/knowledge/ -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_140&rev=1620777697

Last update: 2021/05/12 09:01