

Table of Contents

Version 1.1.0 (V1.1.0_181031)	1
Release	1
Bug fixes	1

Version 1.1.0 (V1.1.0_181031)

Release

2018-11-26

Bug fixes

1. If the data transmission fails when communicating with OSDP, it is transmitted again.
2. The OSDP ID command does not respond if a user changes the OSDP key using Secure I/O 2.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:om120_revision_note_110

Last update: **2021/05/18 08:22**