2024/09/09 20:33 / Version 2.7.6 (V2.7.6.16)

Table of Contents

Version 2.7.6 (V2.7.6.16)	1
Release	1
New Features and Improvements	1
Main fixes	1
Bug fixes	2

2024/09/09 20:33 1/2 Version 2.7.6 (V2.7.6.16)

Version 2.7.6 (V2.7.6.16)

Release

2019-05-20

New Features and Improvements

- 1. Support to the Clear APB for each user.
- 2. Add BioStar 1.x to BioStar 2.x Migration Tool.
- Supports the use of user and event logs from BioStar 1.x in BioStar 2.
- 3. Add the event items to IMAGE LOG menu.
- 4. Add the encryption option to Active Directory.
- 5. Improve that the administrator can change the port 9000 in FastCGI of Port menu.
- **6.** Improve that the time of events is displayed as the time zone, device time, and server time on the alarm email.

Main fixes

- 1. If an administrator set the language to Spanish(Spain), exporting the T&A report in PDF does not work properly.
- 2. If you set an event by selecting the Input (Event Name Change) option in Trigger & Action of the device settings, the event does not work properly as follows:
- DM-20
- 1. The alert does not occur.
- 2. '-1' is displayed instead of the event name set in Real-time Log.
- 3. 'Input detect' is displayed instead of the event name set in Event Log.
- All devices
- 1. The code name is displayed instead of the event name set in DASH BOARD and MONITORING menu.
- 3. Change the recording method for users who do not have access logs.

2024/09/09 20:33 2/2 Version 2.7.6 (V2.7.6.16)

- Displayed in Long-term Idle Users menu.
- Log 'No history' on the Last Entrance Date column.
- 4. When an administrator logs in as the custom level with permissions to a user group, the administrator cannot select the devices and subgroups belonging to the device group in <Delete From Device>.
- 5. Deactivate 'Check the database connection' and 'Generate the database tables' options in the Custom installation window when upgrading the BioStar 2 version.

Bug fixes

- 1. Fixed a security vulnerability by deactivating the 3DES encryption option.
- 2. If an administrator sets the language other than Korean or English, an error occurs when a user logs in and select Help menu.
- 3. The 'Input detect' event that occurred in the interlock zone is displayed as '-1' in Real-time log.
- 3. If an administrator selects a user group when adding an access group, the information and the number of the access group are not output properly.

From:

http://kb.supremainc.com/knowledge/ -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:release note 276

Last update: 2021/05/12 16:31