

Table of Contents

Version 1.2.1 (V1.2.1_160317) 1

Release 1

Bug Fixes 1

Version 1.2.1 (V1.2.1_160317)

Release

2016-03-17

Bug Fixes

1. Logs not transmitting properly when logs in the device reaches the storage limit.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_121

Last update: **2021/05/14 11:53**