

Table of Contents

Version2.8.2(V2.8.2.9)

.....

1

Date

.....

1

New Features

.....

1

Modification function

.....

2

Version2.8.2(V2.8.2.9)

Date

2022-04-25

New Features

- USB File Read Support with Ver.3
- Supports the function of adding Barcode bypass.
- Supports the function of adding Treat as CSN feature
- Supports the function of adding the Smartcard byte order functionality
- Adding support items to the system support information

1. On devices that support Ver.3 (GDPR supported), the following functions have been added to read USB files.

The functions below are applicable if you have previously called the [BS2_SetDataEncryptKey](#) function to change the device's user information encryption key.

The newly added key parameter can be used to specify the key that was set in the past.

- Add API [BS2_GetUserDatabaseInfoFromDirWithKey](#)
- Add API [BS2_GetUserListFromDirWithKey](#)
- Add API [BS2_GetUserInfosFromDirWithKey](#)
- Add API [BS2_GetUserDatasFromDirWithKey](#)
- Add API [BS2_GetUserInfosExFromDirWithKey](#)
- Add API [BS2_GetUserDatasExFromDirWithKey](#)
- Add API [BS2_GetLogFromDirWithKey](#)
- Add API [BS2_GetFilteredLogFromDirWithKey](#)
- Add API [BS2_GetUserSmallInfosFromDirWithKey](#)
- Add API [BS2_GetUserSmallDatasFromDirWithKey](#)
- Add API [BS2_GetUserSmallInfosExFromDirWithKey](#)
- Add API [BS2_GetUserSmallDatasExFromDirWithKey](#)
- Add API [BS2_GetUserInfosFaceExFromDirWithKey](#)
- Add API [BS2_GetUserDatasFaceExFromDirWithKey](#)
- Add API [BS2_GetLogBlobFromDirWithKey](#)
- Add API [BS2_GetLogSmallBlobFromDirWithKey](#)
- Add API [BS2_GetLogSmallBlobExFromDirWithKey](#)

2. Barcode bypass functionality has been added to allow barcode to be subscribed from devices with barcode scan enabled.

- Refer to structure [BS2BarcodeConfig](#)
- Add API [BS2_SetBarcodeScanListener](#)
- Add callback function [OnBarcodeScanned](#)

3. Barcode bypass functionality has been added to allow barcode to be subscribed from devices with barcode scan enabled.

- Refer to structure [BS2BarcodeConfig](#)

4. It has been modified to specify the byte order of the Smartcard.

- Refer to structure [BS2CardConfig](#)
- Refer to API [BS2_GetCardConfig](#)
- Refer to API [BS2_SetCardConfig](#)

5. The system support information for the Smartcard byte order, Treat as CSN functionality has been updated.

- Refer to structure [BS2DeviceCapabilities](#)
- Refer to API [BS2_GetDeviceCapabilities](#)

Modification function

1. libxml2 library dependency removed from SDK.

2. The USB file read function has been modified internally to support Ver.3 (GDPR supported).

The functions below are applicable if you have never changed the device's user information encryption key by calling the [BS2_SetDataEncryptKey](#) function in the past.

The functions below are obtained by decrypting the encryption information to the default key value. The user can invoke the function the same as before

- Refer to API [BS2_GetUserDatabaseInfoFromDir](#)
- Refer to API [BS2_GetUserListFromDir](#)
- Refer to API [BS2_GetUserInfosFromDir](#)
- Refer to API [BS2_GetUserDatasFromDir](#)
- Refer to API [BS2_GetUserInfosExFromDir](#)
- Refer to API [BS2_GetUserDatasExFromDir](#)
- Refer to API [BS2_GetLogFromDir](#)
- Refer to API [BS2_GetFilteredLogFromDir](#)
- Refer to API [BS2_GetUserSmallInfosFromDir](#)
- Refer to API [BS2_GetUserSmallDatasFromDir](#)
- Refer to API [BS2_GetUserSmallInfosExFromDir](#)
- Refer to API [BS2_GetUserSmallDatasExFromDir](#)
- Refer to API [BS2_GetUserInfosFaceExFromDir](#)
- Refer to API [BS2_GetUserDatasFaceExFromDir](#)
- Refer to API [BS2_GetLogBlobFromDir](#)
- Refer to API [BS2_GetLogSmallBlobFromDir](#)
- Refer to API [BS2_GetLogSmallBlobExFromDir](#)

3. The following two APIs for connecting USB have been deprecated.

The context can then be used by calling [BS2_AllocateContext](#) to pass on the generated object.

- Deprecated to API [BS2_AllocateUsbContext](#)
- Deprecated to API [BS2_ReleaseUsbContext](#)

- Refer to API [BS2_AllocateContext](#)
- Refer to API [BS2_ReleaseContext](#)

4. Fix the problem that the device connection is disconnected in case of a simple communication error in SSL connection mode.

From:

<https://kb.supremainc.com/bs2sdk/> - **BioStar 2 Device SDK**

Permanent link:

https://kb.supremainc.com/bs2sdk./doku.php?id=en:release_note_2829

Last update: **2023/08/17 13:31**