

2.5.0 ..... 1



```

* [[BS2_GetIntrusionAlarmZone]] 가
* [[BS2_GetIntrusionAlarmZoneStatus]] 가
* [[BS2_SetIntrusionAlarmZone]] 가
* [[BS2_SetIntrusionAlarmZoneAlarm]] 가
* [[BS2_RemoveIntrusionAlarmZone]] 가
* [[BS2_SetIntrusionAlarmZoneArm]] 가
* [[Configuration API#BS2IntrusionAlarmZoneBlob]] 가

```

4. Ethernet Zone Zone Master BioStar V2.x 가 가  
 (Master ↔ Member) Ethernet TCP Zone 1.x  
 Entrance Limit, Fire Alarm Zone

- [BS2\\_GetDeviceZone](#) 가
- [BS2\\_SetDeviceZone](#) 가
- [BS2\\_RemoveDeviceZone](#) 가
- [BS2\\_SetDeviceZoneAlarm](#) 가
- [BS2DeviceZoneConfig](#) 가

5. USB Export USB  
 Export / Import T&A ( ) BioStar  
 가 USB , USB  
 T&A USB , USB

- [BS2\\_GetUserListFromDir](#) 가
- [BS2\\_GetUserInfosFromDir](#) 가
- [BS2\\_GetLogFromDir](#) 가

5. 가 SDK 가

\* [BS2\\_GetFilteredLogSinceEventId](#) 가

1. BS2\_ScanFingerprint BS2\_ScanFingerprintEx 가가  
 outQuality 가가

```

#include "BS_API.h"

int BS2_ScanFingerprintEx(void* context, uint32_t deviceId, BS2Fingerprint*
finger, uint32_t templateIndex, uint32_t quality, uint8_t templateFormat,
uint32_t* outQuality, OnReadyToScan ptrReadyToScan);

```

2. SSL connect wait time

- 3. Payload size가 Internal Error .
- 4. Packet Loss Packet UDP 가
- 5. C# BS2Schedule . C# (Union ) 가 . BS2Schedule CSP\_BS2Schedule , BS2Schedule BS2\_GetAllAccessSchedule, BS2\_GetAccessSchedule, BS2\_SetAccessSchedule WRAPPER CSP\_BS2\_GetAllAccessSchedule, CSP\_BS2\_GetAccessSchedule, CSP\_BS2\_SetAccessSchedule . CSP\_BS2Schedule scheduleUnion.daily, scheduleUnion.weekly isDaily .
- 6. BS2\_GetFilteredLogSinceEventId 가 . C#
- 7. C# Util GetAll, Get Remove, Set Wrapper Template 가가
- 8. Linux CPU 100% .
- 9. C# BS2CardModelEnum{ODPW, OAPW} 가가 .
- 10. C# Util UnixTimeStamp UTC .

From:

<https://kb.supremainc.com/bs2sdk/> - **BioStar Device SDK**

Permanent link:

[https://kb.supremainc.com/bs2sdk./doku.php?id=ko:release\\_note\\_250&rev=1508283635](https://kb.supremainc.com/bs2sdk./doku.php?id=ko:release_note_250&rev=1508283635)

Last update: **2017/10/18 08:40**