2023/10/25 15:00 1/1 Version 2.6.4 (V2.6.4.1)

Table of Contents

Version 2.6.4 (V2.6.4.1)	
Date	
New Features	
Modified Features	

2023/10/25 15:00 1/2 Version 2.6.4 (V2.6.4.1)

Version 2.6.4 (V2.6.4.1)

Date

2020-02-25

New Features

- Supports the API retrieving logs filtered by EventMask
- Supports DesFire Advanced format setting
- Supports the card type selection feature
- Supports duplicate fingerprints/face check
- 1. The API retrieving logs filtered by Event Mask so that you can use memory efficiently than before.
 - Structure BS2EventSmallBlob has been added
 - API BS2 GetLogSmallBlob has been added
 - API BS2 GetLogSmallBlobFromDir has been added
- 2. DesFire Advanced format setting is now supported.
 - Structure BS2SimpleDeviceInfoEx has been added
 - Structure BS2DesFireCardConfigEx has been added
 - API BS2 GetDesFireCardConfigEx has been added
 - API BS2 SetDesFireCardConfigEx has been added
- **3.** Card type selection is available so that you can select/deselect the card type you want to read fro the device.
 - Structure BS2SystemConfig has been added
 - API BS2 SetSystemConfig has been added
- 4. Duplicate fingerprint and face check is available.
 - Structure BS2FaceConfig has been added
 - API BS2_GetFingerprintConfig has been added
 - API BS2 SetFingerprintConfig has been added
 - Structure BS2FingerprintConfig has been added
 - API BS2 GetFaceConfig has been added
 - API BS2 SetFaceConfig has been added

Modified Features

 ${f 1.}$ Fixed the issue of device malfunctioning and rebooting when BS2Job.numJobs in BS2UserBlobEx

2023/10/25 15:00 2/2 Version 2.6.4 (V2.6.4.1)

exceeds the maximum value 16.

- Refer to structure BS2UserBlobEx
- Refer to API BS2 VerifyUserEx
- Refer to API BS2 IdentifyUserEx
- Refer to API BS2 EnrolUserEx
- Refer to API BS2 VerifyUserSmallEx
- Refer to API BS2_IdentifyUserSmallEx
- Refer to API BS2 EnrollUserSmallEx
- 2. Fixed the issue of BioStation 2 not available for user images.
- 3. Fixed the error BS SDK INVALID CODE SIGN when upgrading SIO2.
- **4.** Fixed the error BS_SDK_ERROR_NOT_SUPPORTED when calling BS2_GetCardModel for BLN2-PAB.
 - Refer to API BS2 GetCardModel
- **5.** Fixed the issue that SDK doesn't recognize device disconnection when the device is constantly disconnected.
- 6. Fixed the issue of Linux SDK crash.

From:

https://kb.supremainc.com/kbtest/ - BioStar 2 Device SDK

Permanent link:

https://kb.supremainc.com/kbtest/doku.php?id=en:release note 264&rev=1595391458

Last update: 2020/07/22 13:17