

2.5.0 1


```

* [[BS2_GetIntrusionAlarmZone]] 가
* [[BS2_GetIntrusionAlarmZoneStatus]] 가
* [[BS2_SetIntrusionAlarmZone]] 가
* [[BS2_SetIntrusionAlarmZoneAlarm]] 가
* [[BS2_RemoveIntrusionAlarmZone]] 가
* [[BS2_SetIntrusionAlarmZoneArm]] 가
* [[Configuration API#BS2IntrusionAlarmZoneBlob]] 가

```

4. Ethernet Zone Zone Master BioStar V2.x 가 가
 (Master ↔ Member) Ethernet TCP Zone 1.x
 Entrance Limit, Fire Alarm Zone

- [BS2_GetDeviceZone](#) 가
- [BS2_SetDeviceZone](#) 가
- [BS2_RemoveDeviceZone](#) 가
- [BS2_SetDeviceZoneAlarm](#) 가
- [BS2DeviceZoneConfig](#) 가

5. USB Export USB
 Export / Import T&A () BioStar
 가 USB , USB
 T&A USB , USB

- [BS2_GetUserListFromDir](#) 가
- [BS2_GetUserInfosFromDir](#) 가
- [BS2_GetLogFromDir](#) 가

5. 가 SDK 가

* [BS2_GetFilteredLogSinceEventId](#) 가

1. BS2_ScanFingerprint BS2_ScanFingerprintEx 가가
 outQuality 가가

```

#include "BS_API.h"

int BS2_ScanFingerprintEx(void* context, uint32_t deviceId, BS2Fingerprint*
finger, uint32_t templateIndex, uint32_t quality, uint8_t templateFormat,
uint32_t* outQuality, OnReadyToScan ptrReadyToScan);

```

2. SSL connect wait time

- 3. Payload size가 Internal Error .
- 4. Packet Loss Packet UDP 가
- 5. C# BS2Schedule . C# (Union) 가 . BS2Schedule CSP_BS2Schedule , BS2Schedule BS2_GetAllAccessSchedule, BS2_GetAccessSchedule, BS2_SetAccessSchedule WRAPPER CSP_BS2_GetAllAccessSchedule, CSP_BS2_GetAccessSchedule, CSP_BS2_SetAccessSchedule . CSP_BS2Schedule scheduleUnion.daily, scheduleUnion.weekly isDaily .
- 6. BS2_GetFilteredLogSinceEventId 가 . C#
- 7. C# Util GetAll, Get Remove, Set Wrapper Template 가가
- 8. Linux CPU 100% .
- 9. C# BS2CardModelEnum{ODPW, OAPW} 가가 .
- 10. C# Util UnixTimeStamp UTC .

From: <https://kb.supremainc.com/kbtest/> - **BioStar Device SDK**

Permanent link: https://kb.supremainc.com/kbtest/doku.php?id=ko:release_note_250&rev=1508283342

Last update: **2017/10/18 08:35**