

Table of Contents

Version 1.2.2 (V1.2.2_180710)	1
Release	1
Bug Fixes	1

Version 1.2.2 (V1.2.2_180710)

Release

2018-07-24

Bug Fixes

1. The device restarts when authentication fails.
2. Modified to limit kernel downgrade based on the hardware version of the device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_122

Last update: **2021/05/28 11:15**