

Table of Contents

Version 1.1.7 (V1.1.7_150805)	1
Release	1
New Features and Improvements	1

Version 1.1.7 (V1.1.7_150805)

Release

2015-08-05

New Features and Improvements

1. Output the NACK signal when SecuBlock error occurs.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_117

Last update: **2021/05/18 09:33**