

Table of Contents

| | |
|-------------------------------------|---|
| Version 1.5.0 (V1.5.0_250805) | 1 |
| Release | 1 |
| New Features and Improvements | 1 |

Version 1.5.0 (V1.5.0_250805)

Release

2025-08-06

- After upgrading the firmware to v1.5.0, it is not able to downgrade to an earlier version of the firmware.
- The XP2-MAPB-H model cannot downgrade to firmware version v1.4.3 or lower.
- The XP2-GKDPB model with hardware v1.2.0 or higher cannot downgrade firmware to lower than v1.4.3. The hardware version can be checked in the **DEVICE** menu of BioStar 2.
- Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.3.1 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (<https://supremainc.com>).

New Features and Improvements

1. Reflects global cybersecurity standards and the latest security requirements.

From:
<https://kb.supremainc.com/knowledge/> -

Permanent link:
https://kb.supremainc.com/knowledge./doku.php?id=en:xp2_revision_note_150

Last update: **2025/09/17 15:19**