

Table of Contents

Version 1.3.0 (V1.3.0_170221)	1
Release	1
Version 1.3.0 (V1.3.0_170201)	1
Release	1
Version 1.3.0 (V1.3.0_170116)	1
Release	1
New Features and Improvements	1

Version 1.3.0 (V1.3.0_170221)

Release

2017-02-21

1. Apply eMMC alternatives (Samsung 8GB D Die to E Die)
2. Fixed issue where the device is restarted (Set Application GPU HW Accelerator as Off)

Version 1.3.0 (V1.3.0_170201)

Release

2017-02-07

1. Add reset code for changing LCD part.

Version 1.3.0 (V1.3.0_170116)

Release

2017-01-16

New Features and Improvements

1. Support elevator control.
2. Support for alphanumeric ID.
3. Support for Secure Communication (SSL & TLS)
4. Private authentication mode can be added on access-on-card.
5. Up to 100,000 cards can be added to blacklist

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_130

Last update: **2021/05/13 14:41**